

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. MD-1012

HABS
MD
17-MARBU,
11-

PLEASANT HILLS
7001 Croom Station Road
Upper Marlboro
Prince Georges County
Maryland

Jack E. Boucher, photographer; 19 April 1990

- MD-1012-1 GENERAL VIEW OF HOUSE IN ENVIRONMENTAL SETTING, LOOKING TO THE NORTH (FRONT) OF THE HOUSE FROM THE DRIVE (GRANARY TO RIGHT)
- MD-1012-2 PERSPECTIVE VIEW OF NORTH (FRONT) LOOKING SOUTH-SOUTHWEST
- MD-1012-3 NORTH (FRONT) ELEVATION
- MD-1012-4 NORTH (FRONT) ELEVATION WITH SCALE
- MD-1012-5 WEST SIDE OF MAIN BLOCK AND NORTH (FRONT) OF WING, LOOKING SOUTH-SOUTHEAST
- MD-1012-6 SOUTH (REAR) ELEVATION
- MD-1012-7 SOUTH (REAR) ELEVATION WITH SCALE
- MD-1012-8 EAST SIDE OF MAIN BLOCK AND SOUTH (REAR), LOOKING NORTHWEST
- MD-1012-9 WEST SIDE OF WING AND SOUTH (REAR), LOOKING NORTHEAST
- MD-1012-10 DETAIL OF WALL NEAR DOORWAY ON NORTH (FRONT), SHOWING INITIALS INSCRIBED IN THE BRICK, WITH SCALE
- MD-1012-11 INTERIOR VIEW LOOKING OUT THROUGH NORTH (FRONT) DOORWAY, SHOWING FANLIGHT AND SIDELIGHTS
- MD-1012-12 INTERIOR VIEW OF STAIRWAY IN SIDE HALL, EAST SIDE OF MAIN BLOCK, LOOKING SOUTH TOWARDS REAR ENTRY
- MD-1012-13 INTERIOR VIEW IN NORTH PARLOR LOOKING SOUTHWEST TOWARDS WEST FIREPLACE WALL AND THROUGH DOORWAY ON SOUTH WALL INTO THE ADJOINING SOUTH PARLOR
- MD-1012-14 INTERIOR VIEW LOOKING NORTHWEST FROM SOUTH PARLOR INTO NORTH PARLOR, SHOWING THE WOOD-GRAINED DOORS
- MD-1012-15 INTERIOR VIEW, DETAIL OF WOOD-GRAINED DOORS IN SOUTH PARLOR

- MD-1012-16 INTERIOR VIEW, DETAIL OF PAINTED ESCUTCHEON ON DOOR FROM HALL
INTO NORTH CHAMBER, SECOND FLOOR
- MD-1012-17 INTERIOR VIEW LOOKING WEST FROM MAIN BLOCK INTO DINING ROOM
LOCATED IN WING, SHOWING MANTEL AND BOXED STAIRWAY
- MD-1012-18 PHOTO-COPY OF HISTORIC VIEW OF NORTH (FRONT) ELEVATION WITH
MEMBERS OF THE HILL FAMILY IN FRONT